

**Consumer Bulletin**  
**Extended Emission Control System Warranty and Repair Reimbursement Program**

Baja is extending the emission control system (ECS) warranty for its Model Year 2006 and 2007 vehicles (including all-terrain vehicles and motorcycles), and certain generators sold by Pep Boys, effective 7/16/10. As part of this program, Baja will also reimburse owners for certain repair expenses previously incurred, as described below.

(1) Extended ECS warranty. Baja is extending the ECS warranty for the Model Year 2006 and 2007 vehicles as follows:

- Off-highway motorcycles and ATVs: additional 30 months from 7/16/2010
- Highway motorcycles: additional 60 months from 7/16/2010
- Generators: additional 24 months from 7/16/2010

Eligible models and engine families are listed in the Tables below. Where a warrantable condition exists, Baja will repair your vehicle at no cost to you, including diagnosis, parts and labor. If an emission-related part on your vehicle is defective, the part will be repaired or replaced by Baja. Your ECS warranty covers components whose failure would increase an engine's emission, including electronic controls, fuel injection system, carburetor, the ignition system, catalytic converter, or any other system utilized in this vehicle to control emissions. Also included may be hoses, connectors and other emission-related assemblies. A list of emission-related parts is provided at <http://www.bajamotorsports.com/documents/CDPartsList.pdf>. Certain terms and conditions of the standard Baja ECS warranty continue to apply, available at <http://www.bajamotorsports.com/documents/OffroadEmissionsWarranty.pdf>

(2) Unpaid Repair Reimbursement: Baja will reimburse reasonable expenses incurred by an owner of a Baja vehicle covered by the Extended ECS warranty program. To be eligible for reimbursement, the repair expenses must have been incurred prior to 7/16/2010, and proof of payment is required. Within 60 days from the date the reimbursement claim is submitted, Baja will either (1) pay the claim; (2) provide the owner, in writing, with a conditional approval, requesting additional information needed in order to validate the claim; or (3) deny the claim with an explanation of the basis for denial and a notice that the owner may obtain further information concerning the Extended Emission-Related Warranty and Repair Reimbursement Program from the U.S. EPA.

For questions regarding this consumer bulletin, or to obtain a repair reimbursement claim form, please call Baja Motorsports toll free at:

(866) 260-8630  
Monday – Friday, 9:00 AM – 7:00 PM EST  
Baja Motorsports  
P.O. Box 61150  
Phoenix, AZ 85082  
[service@bajamotorsports.net](mailto:service@bajamotorsports.net)

You may report questions or concerns regarding compliance with the terms of this Extended ECS warranty program by contacting:

Director, Air Enforcement Division  
U.S. Environmental Protection Agency  
1200 Pennsylvania Avenue., N.W. (2242A)  
Washington, DC 20460  
(202) 564-2260

*Note: This project is being undertaken in connection with the settlement of an enforcement action, United States v. The Pep Boys – Manny, Moe & Jack and Baja, Inc., taken on behalf of the U.S. Environmental Protection Agency under the Clean Air Act.*

<b>Table 1</b>	
<b>Recreational Vehicle Model</b>	<b>Engine Family</b>
<b>Model Year 2006</b>	
BA90/Baja 90, WD50, Wilderness 50	6GDDX0.90NFG
BA150/Baja 150	6CQLX0.15ATV
WD50U, WD50U1, WD90, WD90U/Wilderness 50U, 50U1, 90, 90U / BA49, BA50 / Baja 49, 50	Unknown
DB30/Doodle Bug, Viper, Blitz, Dirt Bug, Racer	6CLGS.09852F
DN150/Dune 150 / BR150, BR150-1 / Reaction 150, 150-1	6AVIX.150SB1
DR49, DR70, DR50, DR50-R/Dirt Runner 49, 70, 50, 50-R	6CGQX.049DB1
DR90/Dirt Runner 90	6CGQX.107DB1
DR125, DR150/Dirt Runner 125, 150	6CGQX.149DB1
MB165, MB165C/Mini Baja 165, 165C, HT65/Heat 65, TR65/Trail 65, BB65/Blaster 65	6CHGS.1961CH
STR125/ Storm	6DDIX0.12NFG
WD250U, WD250UR, WD250U-2/Wilderness 250U, 250UR, 250U-2	6CQLX0.25ATV 6JNHX.229001
X150/ Extreme	6NMRX0.15
X300/ Extreme	6NMRX0.29NFG

**Model Year 2007**

BA49, BA50/Baja 49, 50, WD50, WD50U, WD50U1/Wilderness 50, 50U, 50U1	7LGGX0.07LTF 7AVIX.049FYM
BA90/Baja 90	7FYM.090AM4
BA150/Baja 150	7LGGX.150AA1
BA250/Baja 250	7KYKX.250AM5
BR150, BR150-1/Reaction 150, 150-1, DN150/Dune 150	7DAZX.150EC1 7TJPX.150150
DB30/Doodlebug, Viper, Blitz, Dirt Bug, Racer	7CGQX.100BAA 7CLGS.09852F
DN250/Dune 250	7RUNX.300XM5
DR49, DR70/Dirt Runner 49, 70	7CGQX.049DB1
DR90/Dirt Runner 90, WR90/Warrior 90	7CGQX.107DB1
DR125, DR150/Dirt Runner 125, 150	7CGQX.149DB1
DX70, KCR70*	7COYX.070A01
DX110, KCR110*	7COYX.125A02
MB165, MB165C/Mini Baja 165, 165C, HT65/Heat 65	7CGQX.200CAA
STR125/ Storm	7FYM.125AM4
TR65/Trail 65, BB65/Blaster 65	7CGQX.200GAA
WD90, WD90U/Wilderness 90, 90U	7AVIX.086FYA
WD250U, WD250UR, WD250U-2/Wilderness 250U, 250UR, 250U-2	7LGGX0.250AM5
WD400U/Wilderness 400U	7TMTX.400A01
X250/ Extreme	7XMTX.250DMA

**Table 2**

<b>Highway Motorcycle Model</b>	<b>Engine Family</b>
<b>Model Year 2006</b>	
PX250/Phoenix 250	6DDIC0.23NFG
SC50, SC50-P/Scooter 50, 50-P	6SGMC0.05GSV
SC125/Scooter 125	6ZGNC0.12NFG
SSR200	6ZGNC.197GY1
<b>Model Year 2007</b>	
BV250/ Vision	7TKSC0.25001
PX250/Phoenix 250	7FYMC.250MMA
SC50, SC50-P/Scooter 50, 50-P, RT50-2, RT50-R/Retro 50-2, 50-R	7TMTX.049MC3 7QMGC.049QJ4
SC125, SC150/Scooter 125, 150	7TMTX.150MC2

<b>Table 3</b>	
<b>Generator Model</b>	<b>Engine Family</b>
<b>Model Year 2004</b>	
Jiangsu Jiangdong 3500 Watt*	4JDGS.1961GA
<b>Model Year 2005</b>	
Jiangsu Sumec-Linhai 2500 Watt*	5SLHS.1711GA
Lifan, Dajiang 3500 Watt*	5CLGS.19668F 5CDPS.1961GA
Lifan, Powerful Machinery 2200 Watt*	5CLGS.16368F 5PMES.1731GA
Loncin, Dajiang 5500 Watt*	5CDPS.3892GA 5CGPS.3892GA
<b>Model Year 2006</b>	
Chongqing Weima 9000 Watt*	6CWPS.4202WM
Wenling Jennfeng 3500 Watt*	6WJFS.1961GA
<b>Model Year 2007</b>	
Chongqing Weima 9000 Watt*	7CWPS.4202WM

*\*Requires proof of purchase from Pep Boys.*